

Lead-free soldering

Since 6 October 2004 SANYO Component Europe has banned lead-containing soldering wire from its production.

For the time being the foregoing does not apply to the charger production, where the adjustment process is persisting.

Lead-containing components are being replaced as soon as identical parts are available in lead-free version. This is an on-going process, which is almost completed.

SANYO Component Europe GmbH